



PRODUCT DISCONTINUATION

PD_093_08

!! UPDATE !!

Reason:

Termination of production of SP300V4.0-Exxx-0 Types in Backend Regensburg. **Replacement products are having backend production in Malacca indicated by "V5.0" in the device code**

Original:

Product Discontinuation PD_093_08 dated 2008-08-12

Update:

Ordering codes for replacement products available, supplementation of reason

DISCONTINUED				NEW (REPLACEMENT)			
Device	Ordering Code	Package	Function	Device	Ordering Code	Package	Function
SP300V4.0-E106-0	SP000208318	PG-DSOSP-14-62	TPMS sensor	SP300V5.0-E106-0	on request SP000435430	PG-DSOSP-14-62	TPMS sensor
SP300V4.0-E116-0	SP000208320	PG-DSOSP-14-62	TPMS sensor	SP300V5.0-E116-0	on request SP000477044	PG-DSOSP-14-62	TPMS sensor
SP300V4.0-E136-0	SP000301581	PG-DSOSP-14-62	TPMS sensor	no replacement			
SP300V4.0-E206-0	SP000208319	PG-DSOSP-14-62	TPMS sensor	SP300V5.0-E206-0	on request SP000477042	PG-DSOSP-14-62	TPMS sensor
SP300V4.0-E216-0	SP000311482	PG-DSOSP-14-62	TPMS sensor	SP300V5.0-E216-0	on request SP000477040	PG-DSOSP-14-62	TPMS sensor

■ Last order:	2009-02-15
■ Last delivery:	2009-08-15

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!