

PRODUCT DISCONTINUATION



PD_016_06

DISCONTINUED				NEW (REPLACEMENT)			
Device	Ordering Code *)	Function	Package	Device	Ordering Code *)	Function	Package
HYB25L256160AC-8	SP000015807 Q67100Q4494E401E4	16M x 16	P-TFBGA-54-11	HYB18L256160BC-7.5	SP000015816 Q67100Q1577	16M x 16	P-VFBGA-54-3
HYB25L256160AC-7.5	SP000015810 Q67100Q5178E401E4	16M x 16	P-TFBGA-54-11				
HYE25L256160AC-8	SP000015798 Q67100Q5147E401E4	16M x 16	P-TFBGA-54-11	HYE18L256160BC-7.5	SP000015791 Q67100Q1579	16M x 16	P-VFBGA-54-3
HYE25L256160AC-7.5	SP000015803 Q67100Q5148E401E4	16M x 16	P-TFBGA-54-11				
HYB25L512160AC-8	SP000015797 Q67100Q4922E902E9	32M x 16	P-LFBGA-54-1	HYB18L512160BF-7.5	SP000106008	32M x 16	PG-TFBGA-54-17
HYB25L512160AC-7.5	SP000015812 Q67100Q4921E902E9	32M x 16	P-LFBGA-54-1				
HYE25L512160AC-8	SP000015806 Q67100Q4924E902E9	32M x 16	P-LFBGA-54-1	HYE18L512160BF-7.5	SP000106009	32M x 16	PG-TFBGA-54-17
HYE25L512160AC-7.5	SP000015799 Q67100Q4923E902E9	32M x 16	P-LFBGA-54-1				

*) **SP...** = new ordering code, refer to Info Note 029/05 'Introduction of SAP and i2 for Order Management'

Last order:	31. July 2006
Last delivery:	31. January 2007

Reason: Cessation of 256M / 512M LS14 – non RoHs compliant products